

## Non -Residential Inspection Report

19 Mar 2024	/ Built Structure	25			Complete
Score	18 / 47 (38.3%)	Flagged items	29	Actions	0
Napalis ID					3241862
Conducted or	ı			19 N	/lar 2024 2:09 PM NZDT
Inspected by Built Structures					Built Structures
Location			for	nation	55 Coote Rd Hawke's Bay Napier 4110 New Zealand (-39.4844785688636, 176.91879268591535)
Property Nan	ne				Napier prison
Tenant Name	2	KICIO	~		Toro Waaka
Health and sat	fety Risks on site	01			1 / 1 (100%)
Is the site saf	e to enter?	the			Yes
What are the Retaining wall-a	ivoid				

Flagged items	29 flagged
Inspection / External	
Roof	Poor
Inspection	
Cladding / Brickwork	Poor
Inspection	
Walls / Fences	Poor
Inspection	90.
Gutters & Downpipes	Poor
Inspection	
Doors	Poor
Inspection	Poor
Windows Inspection	Poor
Inspection	
Fascia	Poor
Inspection Fascia Inspection Ceiling & Walls Inspection	Door
Ceiling & Walls	Poor
Inspection Windows & Doors	Poor
Inspection	
Inspection Flooring Inspection	Poor
Inspection	
Electrical Fittings	Poor
Inspection / Bathroom	
Shower	Poor
Inspection	
Toilets	Poor
Inspection	
Sink & Tapware	Poor
Inspection	
Cabinetry	Poor

Ceiling and Walls	Poor
Inspection	
Windows & Doors	Poor
Inspection	
Flooring	Poor
Inspection	
Electrical Fittings	<b>N</b> Poor
Inspection / Kitchen	0,01
Sink & Tapware	Poor
Inspection	
Benchtop	Poor
Inspection	
Cabinetry	Poor
Inspection	×0 <sup>(1)</sup>
Oven	Poor
Inspection	Poor
Rangehood	Poor
Inspection	
Ceiling & Walls	Poor
Inspection	
Windows & Doors	Poor
Inspection	
Inspection Windows & Doors Inspection Flooring	Poor
Inspection	
Electrical Fittings	Poor
Inspection	
Condition	Poor

Inspection	29 flagged, 17 / 46 (36.96%)
Tenanted	Yes
Tenant Notified	Yes
Tenant Present	Yes
Tenant Cooperative	Yes
External	1 flagged, 0 / 1 (0%)
Roof	Poor
Grounds and Garden	Fair
Driveway	Fair
Cladding / Brickwork	Poor
Walls / Fences	Poor
Gutters & Downpipes	Poor
Doors	Poor
Windows	Poor
Fascia	Poor
Fascia       Services       Evacuation Plan	
Evacuation Plan	N/A
Didn't see one	
Heating System	N/A
Heating details	Na
HVAC	N/A
Locks	Fair
Smoke Detectors	N/A
Fire Protection	N/A

Fire Equipment	N/A
BWOF	Good
BWOF Displayed	Yes
BWOF Current	Yes
Security System	Fair
Tenant has cameras	
Lifts	N/A
Foyer	ACT.
Foyer	N/A
Common Areas	1 / 1 (100%)
Common Areas	Yes
Ceiling & Walls	Poor
Windows & Doors	Poor
Flooring	Poor
Electrical Fittings	Poor
Bathroom	1 flagged, 0 / 1 (0%)
Shower	Poor
Bathroom Shower Toilets	Poor
Extractor Fan	N/A
Sink & Tapware	Poor
Cabinetry	Poor
Mirror	N/A
Ceiling and Walls	Poor
Windows & Doors	Poor
Flooring	Poor

Electrical Fittings	Poor
Bathroom 2	
Areas for Concern	
Na	
Kitchen	1 flagged, 0 / 1 (0%)
Sink & Tapware	Poor
Benchtop	Poor
Cabinetry	Poor
Oven	Poor
Rangehood	Poor
Ceiling & Walls	Poor
Windows & Doors	Poor
Flooring	Poor
Electrical Fittings	Poor
Offices	1 / 1 (100%)
Offices Ceiling & Walls	Yes
Ceiling & Walls	Fair
Windows & Doors	Fair
Flooring	Fair
Electrical Fittings	Fair
Stairwell	
Flooring	N/A
Electrical fittings	N/A
Ceiling & Walls	N/A

## **Other Notes**

s 9(2)(k) ] Prison used for tours and escape rooms. Issues tenant termination notice



Photo 1





Photo 8

Photo 14

Photo 20



Photo 13

Photo 7



Photo 19



Photo 25





Photo 32

Photo 33

Photo 27



Photo 3

Photo 9

Photo 15

Photo 21





Photo 10

Photo 22 s 9(2)(k) ]

Photo 34





Photo 5

Photo 11

Photo 23

Photo 35



Photo 36

**Other Notes** 

Additional buildings

**Additional Buildings** 

**How many Buildings** 





Photo 12



Photo 18



Photo 24



Photo 30



N/A

Condition

Referrals

## **Strategic Intent**

Released under the Official Information Act, 1982

## Media summary



Photo 1



Photo 3



Photo 5



Photo 2



Photo 4





Photo 7



Photo 9










Photo 12














Photo 16







Photo 19




Photo 20





Photo 23






Photo 24







Photo 27










Photo 30





Photo 31





Photo 35





Photo 36