



19 November 2009

DTZ New Zealand
PO Box 1545
Wellington

Attention: [s 9(2)(a)]

Dear [s 9(2)(a)]

**GEOTECHNICAL INVESTIGATION AT 58 Akoranga Drive, Northcote,
Auckland**

As discussed in previous correspondence, North Shore City Council engaged a consultant to further investigate the geotechnical situation at 58 Akoranga Drive (Awataha Marae). The primary purpose of this investigation was to better understand the subsurface ground conditions in the vicinity of the damaged wastewater pump station, so that remedial actions can be progressed. This investigation would also help to determine the extent of the ground movement for an area that extends into 58 Akoranga Drive and the causal factors involved. It was agreed that a copy of the report will be made available to LINZ (DTZ).

Please find enclosed a copy of the Riley Consultants Ltd geotechnical investigation. I will be in touch with you in the near future to organise a meeting to discuss the outcomes of the investigation and to progress the remedial actions for the pump station and defective stormwater drainage, as well as responsibility for any works recommended on at 58 Akoranga Drive.

The Awataha Marae are also being provided a copy of the report and will be invited to the meeting.

If you have a preferred date when you (or one of your colleagues) are in Auckland, please let me know asap and I'll try and accommodate this in the timing of the meeting.

Yours faithfully,

[s 9(2)(a)]

Environmental Planning Engineer
NORTH SHORE CITY COUNCIL

Ph.
E-mail

[s 9(2)(a)]

Attached: Riley Geotechnical Investigation