
Survey Number: SO 446319

Date Logged: 22/05/2015 00:00:00

Logged By: CRSPRD

Summary: Data Conversion at 3.11

Status Logged:

Task Logged:

Annotation:

07-Sep-2011 02:11 pm Finlay, Michelle

Dataset Profile

Surveyor profile as provided = 2

Dataset complexity as provided = H

Risk profile as provided = H

Risk profile as validated = H

LOL Validation Reports

C173 TopologyFail

C174 SICPass

SEUW 0.18

C119 SDCFail

SEUW7.85. Fails investigated - linking and adoptions checked. SIC passes.

Manage Adjustment

Free netSEUW0.18

Very bad lines0

Unchecked lines56

Fixed SDCSEUW1.19

Very bad lines4. Very bads have been checked. 6th order mark IT VI DP 15778 is moving 0.09 so is out of terms with the other CSN marks. Coordinates to be readjusted at CMN

Unchecked lines28 - checked

(If required) Control SDCSEUWN/A

Very bad linesNo / Comment

Unchecked linesNo / Comment

Linking Conflicts and Issues

LinkingOK

ConflictsNo / Comment

Issues No / Comment

Advice and Requisitions

Advice received from PCSA or ApproverNo / Comment

RequisitionsM20A - additional vectors required.

M19C - adoptions as specified to be amended. Requested a better image of the top part of SO 1515 which confirms the distance between Peg 1 SO 1515 and Peg XIII B SO 6407 is 226 links (45.46m) rather than 220 links (44.26m).

Notifications to Other Staff

CMN / CTGNo / Comment

Titles - Legal issuesNo / Comment

Survey Number: SO 446319

07-Sep-2011 02:22 pm Finlay, Michelle

Approver: I have requested ChCh support to attach the rescanned portion of SO 1515 as a supporting doc to that plan. If they are unable to do this I have a copy of the image as a pdf file (in an email) which will need to be printed, barcoded, scanned and attached.

12-Sep-2011 04:58 pm George, Ron (AS)

Second vectors not required on W bdys of Sec 7, the calc sheet includes this line. It is noted a bg and partial dist on this W bdy is on SO 6588. Requis unticked.

12-Sep-2011 04:59 pm George, Ron (AS)

System Annotation for Requisition Changes:

Modified M20A For Current Requisition FROM Put On Notice TO Take Off Notice

12-Sep-2011 05:04 pm George, Ron (AS)

System Annotation for Requisition Changes:

Modified Comment for M19C FROM Please check and amend the distance captured as 44.26 between Peg (1) SO 1515 and Peg XIII B SO 6407. The source plan SO 1515 shows this distance as 226 links. Also check and amend the adopted bearings between Peg XIII B SO 6407 and Peg XIV SO 6407 and Peg (1) SO 1515 and Peg (2) SO 1515. The bearing correction applied does not agree with what has been reported. TO Please report further on how the SE bdys (in locality of (1) SO 1515) of Sec 7 have been determined from SO's 1515, 6503 & 6507. Please check and amend the distance captured as 44.26 between Peg (1) SO 1515 and Peg XIII B SO 6407. The source plan SO 1515 shows this distance as 226 links. Also check and amend the adopted bearings between Peg XIII B SO 6407 and Peg XIV SO 6407 and Peg (1) SO 1515 and Peg (2) SO 1515. The bearing correction applied does not agree with what has been reported.

19-Sep-2011 11:20 am Finlay, Michelle

Reqn complied with. Reports are unchanged.

20-Sep-2011 01:47 pm George, Ron (AS)

System Annotation for Supporting Documents and Supporting Documents Changes:

Modified Status for Survey Report FROM Requisitioned TO Valid

Modified Status for Calculation Sheet FROM Requisitioned TO Valid

Modified Status for Area Schedule FROM Requisitioned TO Valid

Modified Status for Mark and Vector Report FROM Requisitioned TO Valid

14-Dec-2011 03:00 pm Lean, Brian

CMN: Done in two parts (unconnected).
